

RP1 250A main and all Subfeed require this new filler starting in July 2019 after previous filler was replaced. replaces all previous blank fillers in this size opening for P1, RP1 and other Lighting Panel applications. Replaces versions.

## Further information

**Industry Online Support (Manuals, Catalogs, Certificates, FAQ, ...)**  
<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>

**Industry Mall (Online ordering system)**  
<https://mall.industry.siemens.com>